Risk Assessment –Lilbourne Minibus Back door exit

Company Name: Lilbourne Parish Council **Date of risk assessment: July 2022 Reviewed May 2026**

What is the Hazard?	Who might be Harmed	Who's responsible	Other exits	Control the risk
Back door blocked by seat. Manufacturer design Needs to be removed for door access	School drivers, volunteer drivers passengers and children	Drivers to confirm they know seat is to be removed and are able to do so Faye Howells-Palin to ensure drivers have a copy of the procedure.	Large side door, front doors either side and windows. (hammer inside to smash windows)	In event of accident/incident leave bus by nearest available/safest exit or window if door blocked. Rear door can be accessed by opening from outside and seat removed.

Risk assessment